



ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಸಂಖ್ಯೆ: ಸಕಾಲ: ಲೋಇ: ನಂ.2: ಉವಿ:ಸು.ಪ್ರ.ಪ:
2024-25 / 769

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರವರ ಕಛೇರಿ
ಲೋಇ, ನಂ.2, ಉತ್ತರ ಉಪವಿಭಾಗ, ಬೆಂಗಳೂರು
ದಿನಾಂಕ: 23/01/2025

ಇವರಿಗೆ:

Secretary,
Vidyanjali International School
Byramma Byrappa Educational Institutions
#5, 2nd Cross Byrappa Layout, Govindapura,
Nagavara Bangalore 560045.

ಮಾನ್ಯರೇ,

ವಿಷಯ:- #5, 2nd Cross Byrappa Layout, Govindapura, Nagavara Bangalore
560045 ವಿಳಾಸದಲ್ಲಿ Byramma Byrappa Educational Institutions
ವತಿಯಿಂದ ನಡೆಸಲಾಗುತ್ತಿರುವ Vidyanjali International School
ಶೈಕ್ಷಣಿಕ ಸಂಸ್ಥೆಯ ಕಟ್ಟಡಕ್ಕೆ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಪ್ರಮಾಣೀಕರಿಸುವ ಬಗ್ಗೆ.

ಉಲ್ಲೇಖ:- 1. ಸರ್ಕಾರದ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ: ಲೋಇ 59 ಬಿಇಡಿ 2019,
ದಿನಾಂಕ:06.05.2022
2. ತಮ್ಮ ಮನವಿ ದಿನಾಂಕ:- 18.01.2025

ಮೇಲಿನ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಉಲ್ಲೇಖ ಪತ್ರ (2) ರಲ್ಲಿ #5, 2nd Cross Byrappa Layout,
Govindapura, Nagavara Bangalore 560045 ವಿಳಾಸದಲ್ಲಿ Byramma Byrappa Educational
Institutions ವತಿಯಿಂದ ನಡೆಸಲಾಗುತ್ತಿರುವ Vidyanjali International School ಶೈಕ್ಷಣಿಕ ಸಂಸ್ಥೆಯ ಕಟ್ಟಡಕ್ಕೆ
ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲು ಕೋರಿರುತ್ತೀರಿ.

ಸರ್ಕಾರದ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ: ಲೋಇ 59 ಬಿಇಡಿ 2019 ದಿನಾಂಕ: 06.05.2022 ರಲ್ಲಿ ಸಹಾಯಕ
ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ರವರು ಶಾಲಾ/ಕಾಲೇಜು ಕಟ್ಟಡಗಳನ್ನು ಪರಿಶೀಲಿಸಿ
Structural stability ನಿರಾಕ್ಷೇಪಣಾ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡಲು ಅಧಿಕಾರ ಪ್ರತ್ಯಾಯೋಜನೆಗೊಳಿಸಿ ಸೂಚಿಸಿರುವುದರಿಂದ
ಪ್ರಸ್ತಾಪಿತ ಕಟ್ಟಡಕ್ಕೆ ಈ ಕೆಳಕಂಡಂತೆ ವರದಿ ನೀಡಲಾಗಿದೆ.

ಪ್ರಸ್ತಾಪಿತ ಕಟ್ಟಡದ ಪರಿವೀಕ್ಷಣೆಯನ್ನು ಕೆಳಗೆ ಸಹಿ ಮಾಡಿದ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಿನಾಂಕ:- 22.01.2025 ರಂದು ಈ ಉಪವಿಭಾಗದ ತಾಂತ್ರಿಕ ತಂಡದೊಂದಿಗೆ ಹಾಗೂ ಹಾಗೂ Infra Support
Engineering Consultants Pvt Ltd (An ISO 9001-2015 Certified Company) ರವರ NDT Report
Dated: 22.01.2025 ಸ್ಪಷ್ಟರಲ್ ವರದಿಯನ್ವಯ #5, 2nd Cross Byrappa Layout, Govindapura, Nagavara
Bangalore 560045 ವಿಳಾಸದಲ್ಲಿ Byramma Byrappa Educational Institutions ವತಿಯಿಂದ
ನಡೆಸಲಾಗುತ್ತಿರುವ Vidyanjali International School ಕಟ್ಟಡವನ್ನು ಪರಿವೀಕ್ಷಣೆ ಮಾಡಿದ್ದು, ಕಟ್ಟಡದ ದೃಢತೆಗೆ

ಸಂಬಂಧಿಸಿದಂತೆ, ಸರ್ಕಾರದ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ: ಲೋಇ 59 ಬಿಇಡಿ 2019 ದಿನಾಂಕ: 06.05.2022 ರಲ್ಲಿ ತಿಳಿಸಿರುವಂತೆ ನೊಂದಾಯಿತ ಸಂಸ್ಥೆಯವರ ಸಹಯೋಗದೊಂದಿಗೆ Infra Support Engineering Consultants Pvt Ltd (An ISO 9001-2015 Certified Company), ವತಿಯಿಂದ 2 ರೀತಿಯ **Non-Destructive** ಪರೀಕ್ಷೆಗಳನ್ನು ಕೈಗೊಳ್ಳಲಾಗಿದ್ದು, ಸದರಿ ಪರೀಕ್ಷೆಯ ವರದಿಯಲ್ಲಿ ಕಟ್ಟಡವು ಉತ್ತಮ ಗುಣಮಟ್ಟದಿಂದ ಕೂಡಿರುವುದು ಎಂದು ಕಂಡುಬಂದಿರುತ್ತದೆ ಮತ್ತು ಫಲಿತಾಂಶಗಳು ತೃಪ್ತಿಕರವಾಗಿರುತ್ತದೆ ಎಂದು ವರದಿಯಲ್ಲಿ ತಿಳಿಸಲಾಗಿರುತ್ತದೆ.

ಸಂಸ್ಥೆಯವರು ಈ ಕೆಳಕಂಡ ದಾಖಲೆಗಳನ್ನು ಸಲ್ಲಿಸಿರುತ್ತಾರೆ.

- ಕಟ್ಟಡದ ನಕ್ಷೆ
- ಸ್ಟೆಬಿಲಿಟಿ ರಿಪೋರ್ಟ್
- ಕಂದಾಯ ರಸೀದಿ

ಷರಾ: ಕಟ್ಟಡದಲ್ಲಿ ಈ ಕೆಳಕಂಡ ಕೆಲಸಗಳನ್ನು ಆದ್ಯತೆಯ ಮೇರೆಗೆ ಕೈಗೊಳ್ಳಲು ಸಂಸ್ಥೆಯವರಿಗೆ ಸೂಚಿಸಲಾಗಿದೆ.

- Painting of the entire building and General periodical maintenance for the building to be carried out.
- Any modifications, Additions & Alterations must be carried out under strict technical guidance and supervision.
- Prevent movement of students at Terrace and safety measures to be taken.

ಮುಂದುವರೆದು, ಉಲ್ಲೇಖ (1) ರ ಸರ್ಕಾರದ ಸುತ್ತೋಲೆಯನ್ವಯ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡಲು ನಿಗದಿಪಡಿಸಿರುವ ಶುಲ್ಕ ಒಟ್ಟು ರೂ. 5000/- (ರೂ.ಐದು ಸಾವಿರ ರೂಪಾಯಿಗಳು ಮಾತ್ರ) ಗಳನ್ನು ಡಿ.ಡಿ. ಮುಖೇನ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ಲೋ.ಇ, ನಂ.2, ಉತ್ತರ ಉಪವಿಭಾಗ, ಬೆಂಗಳೂರು ರವರ ಹೆಸರಿನಲ್ಲಿ Canara Bank ಡಿ.ಡಿ. ಸಂಖ್ಯೆ 404567 ದಿನಾಂಕ: 23.01.2025 ರಲ್ಲಿ ಪಾವತಿಸಿರುತ್ತಾರೆ.

ಪ್ರಸ್ತಾಪಿತ ಕಟ್ಟಡದ Non - Structural Elements (Infrastructural facilities) ಗೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಸಿವಿಲ್ ಇಂಜಿನಿಯರ್, ಆರೋಗ್ಯಾಧಿಕಾರಿ, ಕಂದಾಯ ಅಧಿಕಾರಿ, ಮನಃಶಾಸ್ತ್ರಜ್ಞ, ಸ್ಥಳೀಯ ಸಂಸ್ಥೆಯ ಅಧಿಕಾರಿಗಳನ್ನೊಳಗೊಂಡ ಪರೀಕ್ಷಾ ತಂಡದವತಿಯಿಂದ ಪರಿಶೀಲಿಸಿ ನಿರಾಕ್ಷೇಪಣಾ ಪತ್ರವನ್ನು ಪಡೆಯತಕ್ಕದ್ದು ಹಾಗೂ Fire safety Certificate ಅನ್ನು ಮುಖ್ಯ ಅಗ್ನಿಶಾಮಕ ಅಧಿಕಾರಿಯವರಿಂದ ಪಡೆಯಬೇಕಾಗಿರುತ್ತದೆ.

ಸದರಿ ಸಂಸ್ಥೆಯವರು ನೀಡಿರುವ ಎಲ್ಲಾ ದಾಖಲೆಗಳನ್ನು ಪರಿಶೀಲಿಸಿ, ಕಟ್ಟಡವನ್ನು ಪರಿವೀಕ್ಷಿಸಿ, **#5, 2nd Cross Byrappa Layout, Govindapura, Nagavara Bangalore 560045** ವಿಳಾಸದಲ್ಲಿ **Byramma Byrappa Educational Institutions** ವತಿಯಿಂದ ನಡೆಸಲಾಗುತ್ತಿರುವ **Vidyanjali International School**, ಶೈಕ್ಷಣಿಕ ಕಟ್ಟಡವು **Structurally Stable** ಇದೆ ಎಂದು ನಿರಾಕ್ಷೇಪಣಾ ಪತ್ರವನ್ನು ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು,

ಲೋಇ., ನಂ.2, ಉತ್ತರ ಉಪವಿಭಾಗ,

ಬೆಂಗಳೂರು.

(TRANSLATION FROM KANNADA TO ENGLISH)

LOGO OF GOVERNMENT OF KARNATAKA
GOVERNMENT OF KARNATAKA
Public Works Department

No. SaKaA:PWD: No.2:SD:Su.Pra.Sa:
2024-25/769

Office of the Assistant Executive Engineer
P.W.D. No.2, North Sub-Division, Bangalore
Date : 23/01/2025

To
Secretary,
Vidyanjali International School,
Byamma Byrappa Educational Institutions
#5, 2nd Cross, Byrappa Layout, Govindapura,
Nagavara, Bengaluru – 560045

Sir,


Sub : Regarding issue of Building Safety Certificate for Educational Institution
Vidyanjali International School run by Byamma Byrappa Educational
Institutions located at #5, 2nd Cross, Byrappa Layout, Govindapura,
Nagavara, Bengaluru – 560045

Reference : 1. Government Circular No.: PWD 59 BED 2019, Dated 06-05-2022
2. Request letter dated : 18-01-2025

As per the above subject, reference (2) the Educational Institution **Vidyanjali International School** run by **Byamma Byrappa Educational Institutions** located at #5, 2nd Cross, Byrappa Layout, Govindapura, Nagavara, Bengaluru – 560045 has requested for issuance of the Building Safety certificate.

As per the Reference (1) of the Government Circular No.: PWD 59 BED 2019, Dated 06-05-2022, the Assistant Executive Engineer, Public Works Department has inspected the School/College building and No Objection certificate for issuing the Structural stability with the powers to execute has submitted the below mentioned report.

The Assistant Executive Engineer has re-inspected the suggested building dated :- 22.01.2025 along the team of technicians from this Sub-division and as per the NDT report dated : 22.01.2025 by Infra Support Engineering Consultants Pvt. Ltd. (An ISO 9001-2015 certified Company) the Structural report for **Vidyanjali International School** run by **Byamma Byrappa Educational Institutions** located at #5, 2nd Cross, Byrappa Layout, Govindapura, Nagavara, Bengaluru – 560045, the building was re inspected, the structural stability related, as per the Government Circular No.: PWD 59 BED 2019, Dated 06-05-2022 the registered Institution and support of Infra Support Engineering Consultants Pvt. Ltd. (An ISO 9001-2015 certified Company who have conducted 2 types of Non-Destructive tests conducted.



As per the Report submitted it is found that the existing building is in good condition and results are satisfactory.

The Institution has submitted the following documents :

- Building Plan
- Stability Report
- Tax Receipt

Remarks : The Institution has been informed about the following works to be taken up with priority for the building

- Painting of the entire building and General periodical maintenance for the building to be carried out.
- Any modifications, Additions & Alterations must be carried out under strict technical guidance and supervision.
- Prevent movement of students at Terrace and safety measures to be taken.

According to the Government Circular (1) rule the said Fee of amount Rs. 5000/- (Rupees Five Thousand Only) for the issue of Building safety certificate has been paid vide DD. No. : 404567 Dated : 23.01.2025 drawn from Canara Bank in favour of Assistant Executive Engineer, P.W.D., No. 2, North Sub-division, Bengaluru has been submitted to this office.


With regard to the said building Non-structural Elements (Infrastructural facilities) Civil Engineer, Medical Officer, Revenue Officer, Psychologist, along with the Local Society officers along with the team to conduct test for No objection certificate has to be obtained and Fire Safety Certificate has to be obtained from the Chief fire Officer.

The Educational building Vidyanjali International School run by Byamma Byrappa Educational Institutions located at #5, 2nd Cross, Byrappa Layout, Govindapura, Nagavara, Bengaluru – 560045 is found to be Structurally Stable and being issued the No objection Certificate based on the records submitted by the Institution and verified.

Yours faithfully

Sd/-

Assistant Executive Engineer
P.W.D. No. 2, Norsstth Sub-Division,
Bangalore



Translated by Me :



ATTESTED BY ME


RATNA. N.
B.Com., LL.B.,
Advocate & Notary Public
GOVT. OF INDIA
No. 500/E, Shree Complex, 8th Main, 4th Stage,
Basaveshwaranagar, Bengaluru-560 079
Mob : 98801 96680

23/09/2026